STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING			OMB NO. 0938-03 (X3) DATE SURVEY COMPLETED 11/12/2013	
		445292			111		
NAME OF I	PROVIDER OR SUPPLIER	<u></u>	<u> </u>	STREET ADDRESS, CITY, STATE, ZIP CODE		12/2013	
BEECH	REE MANOR			240 HOSPITAL LANE, PO BOX 300 JELLICO, TN 37762			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPI DEFICIENCY)	ULD BE	(X5) COMPLETIN DATE	
K 027 SS=D	Door openings in smoke barriers have at least a 20-minute fire protection rating or are at least 1¾-inch thick solid bonded wood core. Non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. Horizontal sliding doors comply with 7.2.1.14. Doors are self-closing or automatic closing in accordance with 19.2.2.2.6. Swinging doors are		K 027	(I.) No residents are or were affected absence of self-closures on the boiler	room	11/14/20	
				doors. Self closure devices were insta 3 boiler room doors located in the 200 shower room, in the 300 hall shower in in the dietary (kitchen) room, on Thur November 14, 2013.	ocated in the 200 hall 300 hall shower room, and n) room, on Thursday,		
	not required to swi latching is not requ 19.3.7.7	ng with egress and positive lired. 19.3.7.5, 19.3.7.6,		(2.) The boiler room doors were and a in the 200 and 300 hall shower rooms kitchen. The shower rooms are key-p and inaccessible to residents unless th accompanied by a staff person. The k doors are locked and inaccessible to a other than dietary staff. Residents ha	and in the ad secured ley are itchen nyone		
į	Based on observa	is not met as evidenced by: ition, the facility failed to have n hazardous areas.		access to either of these three boiler without being with a staff person.			
:	revealed that 3 of 3 self-closing;	le: le: livember 12, 2013 at 12:00 p.m. B boiler room doors were not leated in the 200 Half shower		(3.) Due to the historical location of the rooms, these entry doors remain inaction any resident without a staff person accompanying them. Self-closure devinstalled on each of these three doors November 14, 2013.	cessible to vices were	: : :	
:	room. 2. Boiler room loo room.	cated in the 300 Hall shower cated in the dietary room.		(4.)The Maintenance Director or his of monitor all self-closing doors for propfunctioning and shall update or repair deemed necessary.	er	 	
	director and ackno	re verified by the maintenance wledged by the administrator ference on November 12,					
ORAJORY	DIRECTOR'S OR PROVI	DER/SUPPLIER REPRESENTATIVE'S SIGN	JATURF	TITLE		(X6) DATE	
1	A	Euld		Edministration	//	1/25/20	
deficienc	y statement ending with	an asterisk (*) denotes a deficiency whi	ich the insti	tution may be excused from correcting provi for nursing homes, the findings stated above	ding it is dete	mined tha	

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 11/15/2013